
From: John Cima (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=JOHN171]
Sent: 3/30/2015 10:46:05 AM
To: Jeffrey R Marcell (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Jeff136]
Subject: RE: 03-24-15 GAI-Dominion Possum Point Weekly Meeting Minutes

Thanks Jeff....good news on the Pond E dewatering activities with no PH or TSS issues!

John

John A. Cima, P.E.

Consulting Engineer

Power Generation Engineering

Dominion Resources Services, Inc.

5000 Dominion Boulevard

Glen Allen, VA 23060

(PH)804-273-3045; (FAX)804-273-2876; (CELL)804-912-7534

From: Jeffrey R Marcell (Generation - 3)
Sent: Monday, March 30, 2015 10:44 AM
To: John Cima (Generation - 34)
Cc: Bob Jackson (Generation - 34); 'Mike Lott'; 'Don Spaeder'; 'Scott Quinlan'; 'Wes Wolf'; 'Kenneth Kinder'; 'Tyler Hays'; 'Jason Monnell'; 'Charlie Straley'; 'John Klamut'; Michael A Glagola (Generation - 34)
Subject: RE: 03-24-15 GAI-Dominion Possum Point Weekly Meeting Minutes

John,

I'm not aware, nor have I seen, a pipe in the SW corner of E Pond.

Jeff Marcell

00009814

Environmental Supervisor

Possum Point Power Station

Ladysmith & Remington CT Sites

703-441-3813 (phone)

8-795-3813 (tie)

703-441-3897 (fax)

From: John Cima (Generation - 34)

Sent: Monday, March 30, 2015 10:40 AM

To: 'John Klamut'; Michael A Glagola (Generation - 34)

Cc: Jeffrey R Marcell (Generation - 3); Bob Jackson (Generation - 34); 'Mike Lott'; 'Don Spaeder'; 'Scott Quinlan'; 'Wes Wolf'; 'Kenneth Kinder'; 'Tyler Hays'; 'Jason Monnell'; 'Charlie Straley'

Subject: RE: 03-24-15 GAI-Dominion Possum Point Weekly Meeting Minutes

John/Mike,

We have reviewed the 1967 design drawing for Ash Pond E and confirmed that there were plans for a 24" CMP below the southwest corner of the embankment. We have never seen this pipe in our inspections nor do we know if was ever installed. We think it may have been for temporary diversion of storm water flows during pond construction, but we cannot confirm this. If it were installed, I suspect it was grouted after completion of the dikes and the current outfall structure. Jeff Marcell – are you aware of such a pipe under the SW corner of the Pond E dike? If so, please let me know.

The 1967 design drawings also show a bottom ash toe-drain in the lower reaches of the downstream slope of the dikes but we have never seen this in our inspections. Please let me know if you need anything else.

Regards,

John

John A. Cima, P.E.

Consulting Engineer

Power Generation Engineering

Dominion Resources Services, Inc.

5000 Dominion Boulevard

Glen Allen, VA 23060

(PH)804-273-3045; (FAX)804-273-2876; (CELL)804-912-7534

From: John Klamut [<mailto:J.Klamut@gaiconsultants.com>]

Sent: Sunday, March 29, 2015 12:17 PM

To: Michael A Glagola (Generation - 34)

Cc: Bob Jackson (Generation - 34); John Cima (Generation - 34); Mike Lott; Don Spaeder; Scott Quinlan; Wes Wolf; Kenneth Kinder; Tyler Hays; Jason Monnell; Charlie Straley

Subject: 03-24-15 GAI-Dominion Possum Point Weekly Meeting Minutes

Mike,

Attached are the meeting minutes from the GAI-Dominion weekly meeting held Tuesday, March 24th. Please let me know if you have any comments.

Thanks,

John R. Klamut, P.E.
Engineering Manager

GAI Consultants, Inc.

4200 Triangle Lane, Export, PA 15632-1358

724.387.2170 ext. 2707 | C 724.421.6740 |     



transforming ideas into reality® since 1958 | gaiconsultants.com

00009816

CONFIDENTIALITY NOTICE: This communication contains confidential information belonging to the sender and may be legally privileged. This communication is solely for the use of its intended recipient. If you are not the intended recipient, inform the sender of the error and remove this email from your system. If this transmission includes any technical information, design data, and/or recommendations, they are provided only as a matter of convenience and may not be used for final design and/or construction.